



Firmware Version: 1.0.0.8
Published: Apr 1, 2010

Content:

Revision History and System Requirement:.....	2
New Features:	2
Problems Fixed:	3
Known Issues:	4
Related Documentation:	4

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.0.0.8	01-April-10	DWL-8600AP	A1G
V1.0.0.6	09-Dec-09	DWL-8600AP	A1G

New Features:

Firmware Version	New Features
V1.0.0.8	<ol style="list-style-type: none">1. Disabled DFS band support for US and JP2. Removed channel 14 for JP
V1.0.0.6	Initial Release, please refer to DWL-8600AP External Specification for features

Problems Fixed:

Firmware Version	Problems Fixed
V1.0.0.8	<ol style="list-style-type: none"> 1. Sometimes AP stops passing DHCP to the clients. AP need to be rebooted to fix the issue (AP will work fine after rebooting) [DI2010010500002] <ul style="list-style-type: none"> I Need to disable broadcast key refresh for bug fixed I The broadcast key is separate from the unicast key and disabling refresh on the broadcast key does not affect the processing of the unicast key. If the broadcast key refresh is disabled, it means that the broadcast traffic will continue to get encrypted using the fixed key. I The unicast traffic (user data) is encrypted using unicast key and disabling broadcast key refresh will not impact unicast traffic encryption. 2. When use Microsoft Windows 2008 server as DHCP and RADIUS Server. If configure the switch for RADIUS accounting, but don't enable radius accounting on the RADIUS server. The clients can connect normally at the beginning, but after several hours (< 1 day), the clients cannot authenticate successfully The issue is due to being out of RADIUS buffers on the switch that handles RADIUS accounting. [DI2010012900009]
V1.0.0.6	None, initial release

Known Issues:

Firmware Version	Issues
V1.0.0.8	None
V1.0.0.6	None

Related Documentation:

- DWS-4000 Series User Manual
- DWS-4000 Series & DWL-8600AP CLI Manual
- DWL-8600AP Unified AP Guide