

Firmware Version: V4.7.2.9 Published: Feb 07, 2020

### **Copyright Notice**

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

#### Disclaimer

**D-Link** 

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

#### **Limitations of Liability**

UNDER NO CIRCUMSTANCES SHALL D-LINK OR ITS SUPPLIERS BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE D-LINK PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF D-LINK IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, D-LINK WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. D-LINK WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT D-LINK RECEIVED FROM THE END-USER FOR THE PRODUCT.

### **Content:**

Revision History and System Requirement:	
New Features:	2
Problems Fixed:	3
Known Issues:	
CLI Commands	5
Related Documentation:	6





# **Revision History and System Requirement:**

FW Version	Date	Model	HW	MD5 CHECKSUM
V4.7.2.9	07-Feb-2020	DWL-6620APS	A1	b7bb52db09ebbda3d37919090297c72d

## **New Features:**

Firmware Version	New Features
V4.7.2.9	<ol> <li>WPA3</li> <li>Default Password change</li> <li>Note: Due to memory partition reconstruct, after upgrading to v4.7.2.9:         <ul> <li>a. System will reset to factory default.</li> <li>b. Downgrade to v4.7.2.6 or lower version is not allowed.</li> <li>c. Load lower version config file is not allowed.</li> </ul> </li> </ol>
V4.7.2.5	<ol> <li>Support WDS without security.</li> <li>Support IP &amp; MAC address ACL under managed mode.</li> <li>Support DHCP offer/ACK to Unicast function.</li> <li>Support QoS Bandwidth Control.</li> <li>Support Wireless Multicast Forwarding.</li> <li>Support Management IPv6.</li> <li>Support Load Balancing.</li> <li>Support Airtime Fairness. Enable/Disable button is also available.</li> <li>Support D-Link Discovery Protocol (DDP) so that the DWL-X620AP can be discovered and managed by D-Link Network Assistant (DNA).</li> <li>Enhancement to skip manually factory reset while firmware upgrade.</li> <li>For example:</li> <li>V4.7.0.10 &gt; V4.7.2.5, manually reset system to factory default is needed.</li> <li>V4.7.2.5 &gt; V4.7.0.10 (or lower version), manually reset system to factory default is needed.</li> </ol>
V4.7.0.10	The first release





## **Problems Fixed:**

Firmware Version	Problems Fixed
	1. DI20190205000001/ DI20190306000002 WMF issues.
	2. DI20190205000002/ DI20190306000005 Multicast to Unicast feature does not change the destination MAC address from multicast packets to unicast address.
	3. DI20190220000003/ DI20190311000011 AP reloads configuration when AP loses management session, and it caused wireless client disconnection.
	4. DI20190227000004/ DI20190315000002 WLAN utilization 0% issue.
V4.7.2.9	5. DI20190226000005/ HQ20190304000011 All parameters in WMM/WME IE becomes 0 after DWC-2k manages DWL-6620APS.
	6. DI20190516000003 /HQ20190528000011 Showing Radar status info on controller.
	7. DI20190219000008/ HQ20190223000009 Basic rate issue.
	8. Roaming issue on DWL-6620APS/7620AP. When wireless client roams from AP to AP2, after wireless client connects to AP1 again, wireless client can't access Internet.
	01. Fix Bug: Managed Mode - after Controller reboot, AP doesn't do CP again
	02. Fix Bug: Accept Item (DKP1810013-0084) - CLI - set show the error messag (VBG19010632)
	03. Fix Bug: Accept Item (DKP1810013-0093) - Events has smart antenna message (VBG19010623)
	04. Fix Bug: Accept Item (DKP1810013-0050) - Managed Mode - DUT UI cannot ge the force roaming setting from DWC-2000
	(VBG19010588)
V4.7.2.5	05. Fix Bug: Accept Item (DKP1810013-0116) - Managed Mode - Band Steer setting doesn't copy to UI (VBG19010618)
	06. Fix Bug: CLI - Incorrect Radio wlan ID
	07. Fix Bug: tx-power default value is incorrect
	08. Fix Bug: U-APSD doesn't work on Managed Mode and Standalone Mode
	09. Fix Bug: DI20190207000003/ HQ20190213000012 [DWL-6620APS] Beacon Interval became 200 msec if the number of SSID is 9 or more (#60042)
	10. Fix Bug: DNA (D-Link Network Assistant) not work, firmware upgrade part
	11. Fix Bug: LAN crash after receiving special ipv6 packet
green	

# **D-Link**

	12. Fix Bug: DI20190207000001 [DWL-6620APS] There is no Radius Fail Through feature (#60051)
	13. Fix Bug: CLI - "set system led off" doesn't turn off WiFi LED
	14. Fix Bug: LED Off doesn't turn off WiFi LED
	15. Fix Bug: CLI name should use Web UI Hostname
	16. Fix Bug: Standalone - Incorrect ATF string
	17. Hide Multicast to Unicast function
	18. DI20190207000003/ HQ20190213000012 [DWL-6620APS] Beacon Interval
	became 200 msec if the number of SSID is 9 or more (#60042)
	19. Fix Bug: Japan Domain fail to change channel (HQ20180906000008) (Mantis ID:0057993)
	20. Fix Bug: UI accepts invalid Subnet Mask and Gateway (HQ20180709000005) (Mantis ID:0057245)
	21. Fix: Enable the DFS function of JP domain (HQ20180705000002)
	22. Fix Bug: Managed Mode - VLAN + Captive Portal not work
	(HQ20180711000010) (Mantis ID: 0056637)
V4.7.0.10	The first release

## **Known Issues:**

	Firmware Version	Issues
	V4.7.2.9	1. Dynamic VLAN is not working.
	V4.7.2.5	<ul> <li>[DTrack cases]</li> <li>1. DI20190205000001/ HQ20190218000005 (Wireless multicast forwarding) (#60090)</li> <li>2. DI20190205000002/ HQ20190214000002 Mulicast to Unicast feature does not change the destination MAC address from multicast packets to unicast address (#60054) (Hidden via GUI on v4720.)</li> <li>3. DI2019021400005/ HQ2019030400027 [DWL-6620APS] DFS changes the channel to W56 when AP booted up with W56 channel, even if other Auto Eligible channels on W53 are not blocked (#60283)</li> <li>4. DI2019022000003/ HQ2019022300010 [DWC-2000/DWL-6600AP] AP reloads configuration when AP loses management session, and it caused wireless client disconnection (#60279)</li> <li>5. DI20190227000004/ HQ2019030400015 WLAN utilization 0% issue</li> </ul>
dlink	reen	

# **D-Link**

	6. DI20190226000005/ HQ20190304000011 all parameters in WMM/WME IE
	becomes 0 after DWC-2k manages DWL-6620APS
	1. When 802.11ac wireless clients associate with a DWL-6620APS in managed
	mode, the clients will be shown as 802.11n clients on the DWC-2000.
	2. The DWL-6620APS won't be changed to Standalone mode once losing
	association with the controller.
V4.7.0.10	3. When enabling Dynamic VLAN feature, the wireless client could not be
	assigned proper VLAN ID if not configure use_tunneled_reply = yes on the
	FreeRadius server.
	4. Using iPerf to measure the performance, the throughput could be low when
	the packet size is very small such as 128 or 88 bytes.

Command	Action
get managed-ap	Get information about switches that can discove and manage the AP.
get management	<ul> <li>View the following information about the management interface on the AP:</li> <li>VLAN ID</li> <li>Interface name</li> <li>Static IP address (if DHCP is not used)</li> <li>Static subnet mask</li> <li>IP address</li> <li>Subnet mask</li> <li>MAC address</li> <li>DHCP status</li> </ul>
get management dhcp-status	View the connection type.
set management dhcp-status on	Use DHCP as the connection type.
set management dhcp-status off	Use Static IP as the connection type.
get management static-ip	View the static IP address.
get management static-mask	View the subnet address.
get management vlan-id	View management VLAN ID.
set management vlan-id 1~4094	Set management VLAN ID.
reboot	Reboot the system.
factory-reset	Return to factory default setting.
get system led	View system LED status.

## **CLI Commands**



### **DWL-6620APS Firmware Release Notes**

	Status 1: Turned on.
	Status 0: Turn off.
	Turn on system LED.
set system led on	Turn off all system LED.
set system led off	After setting command, need to type the command
save-running	save-running to and then reboot to make the setting
	effective.

# **Related Documentation:**

- DWL-X600AP\_3610AP\_8610AP\_6610AP \_6700AP\_8710AP\_x620AP\_Unified\_AP\_Manual\_v6.61.pdf

