



Firmware Version: V1.02.02
Prom Code Version:
Published Date: 2016/5/09

Content:

Upgrading Instructions:..... 2
New Features:..... 2
Problems Fixed: 3
Known Issues: 3
Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.02.02	2016/05/09	DCS-5000L	A1
V1.01.01	2015/11/04	DCS-5000L	A1
V1.00.21	2015/10/05	DCS-5000L	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.02.02	<ol style="list-style-type: none"> 1. Update Mydlink Agent to 2.0.20-b25. 2. Watch live streaming using a web browser such as Edge, IE, Firefox, Chrome or Safari supported by Adobe Flash Player. 3. Change default live view to Flash mode. 4. Change the HTTPs self-signed certificate to SHA2 algorithms. 5. Support to send the email notification to multiple email addresses. Note: Multiple recipients must be separated by a semicolon, ';' 6. Change the default system time to 2016-01-01. 7. Change the copyright year in the web-UI to 2016. 8. Upgraded OpenSSL to 1.0.1q 9. Add the authentication mechanism for CGI command: config/stream_info.cgi.
V1.01.01	<ol style="list-style-type: none"> 1. Update Agent to 2.0.20-b06
V1.00.21	<ol style="list-style-type: none"> 1. Initial Release

Problems Fixed:

Firmware Version	Problems Fixed
V1.02.02	<ol style="list-style-type: none"> 1. Fixed CSRF vulnerability for the camera's web-UI (Exclude CGI APIs). 2. Fixed an issue that Time zone setting for Minsk should be GMT+3. 3. Fixed an issue that Daylight saving time may not be set correctly for the southern hemisphere. 4. Fixed an issue where IP Camera blocks CGI request from Chrome and Edge. 5. Fixed the "RSA-CRT key leaks" vulnerability.
V1.01.01	<ol style="list-style-type: none"> 1. Updated Direct Mode behavior to support concurrent client/AP mode
	<ol style="list-style-type: none"> 1.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A