



Firmware Version: V1.25_4912

Prom Code Version:

Published Date: 2015/3/12

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	6
Known Issues:	6
Related Documentation:	6





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.25_4912	2015/3/12	DCS-942L	A1~A4
V1.24_4408	2014/10/8	DCS-942L	A1~A4
V1.23_3040	2014/1/23	DCS-942L	A1~A4
V1.22_2825	2013/7/24	DCS-942L	A1~A4
V1.21_2811	2013/6/21	DCS-942L	A1~A4
V1.20_2421	2013/3/29	DCS-942L	A1~A4
V1.12_1628 (EU) V1.12_1608 (WW)	2012/7/23	DCS-942L	A1~A3
V1.11_1426	2012/5/9	DCS-942L	A1~A3
V1.00	2011/8	DCS-942L	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

- 1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
- 2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
- 3. Click Browse... and specify the firmware file.
- 3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.25_4912	1. Upgrade mydlink agent to v2.0.19-b06
	1. Upgrade mydlink agent to v2.0.18-b11
	2. Support Windows 8.1/IE11 and MAC OS X10.9/Safari7
	3. The SD card can be recognized properly when formatting SD card by
V1.24_4408	selecting default allocation unit size on Windows OS
	4. To improve the image quality (NOTE: The image settings will be in effect after
	factory reset.)
	5. Support new NIPCA CGI "/admin/videoclip.cgi" for Video Clip function
	1. Upgrade mydlink agent to v2.0.17-b42
V1.23 3404	2. Support schedule reboot
V1.23_3404	3. Support DDNS server address text input (currently only accept
	<u>www.dlinkddns.com</u> and <u>www.DynDNS.org</u> .)



D-Link[®]

DCS-942L Firmware Release Notes

	T			
	4. Support Windows 8/ IE11			
	5. Refine the NTP sync mechanism			
	1. Support 2-way audio for portal and App			
	2. Combine two firmware versions into one firmware.			
	3. Support Portuguese language.			
V1.22_2825	4. Change the SD recording video clip file format default setting from avi to			
V1.22_2025	mp4.			
	5. Refine the available HTTP/RTSP/HTTPS port range and external			
	HTTP/RTSP/HTTPS port range as 1~65535.			
	6. mydlink Agent: 2.0.17-b21.			
V1.21_2811	1. Upgrade to UPnP v1.6.18.			
V1.21_2011	2. mydlink Agent: 2.0.17-B15			
	Firmware V1.20_2421 is only supported by wizard v1.02.10 or above.			
	1. Support HTTPS			
	Support HTTPS Web Pages (not include Live Streaming)			
	Support HTTPS Port and HTTPS External Port Setting			
	■ Certification management			
	WebUI for HTTPS connection (streaming keep on HTTP)			
	■ Configure/control under HTTPS			
	2. Support IPv6			
	■ IPv6 certification			
	■ IPv6 live view			
	3. Support ONVIF v2.2			
	 ONVIF Profile S Certification 			
V1.20_2421	Add Search Domain field for network setting			
V1.2U_2421	Add Set NTP Server from DHCP for NTP Sync			
	■ Frame rate support 6 fps			
	4. Support AAC audio			
	■ RTSP with AAC			
	■ NIPCA Audio CGIs, /audio/ACAS-AAC.cgi			
	5. Support .mp4 file format with AAC			
	■ SD recording			
	■ Video clip			
	6. Support Apple HTTP Live Streaming			
	7. Support IP Filtering			
	8. Support Sound Detection			
	9. Support Schedule on Day/Nigh Mode			
	10. Support no separated file on SD recording trigger by motion			





Enhancement:

- 1. Enhance NCSPlugin for live view
 - Windows
 - Mac OS X
- 2. Refine the DDNS timeout

DDNS update interval:

Case 1: If DDNS can be connected successfully.

The reload interval will be a fixed time as DDNS timeout, and the valid range is between 24 and 65535.

Case 2: If DDNS is failed to be connected.

The retry interval will be an increasing time as 30 seconds, 60 seconds, 120 seconds, 240 seconds, 480 seconds, and then keeping retrying every 900 seconds until the DDNS can be connected.

3. Refine the interval for Video Clip/Snapshot feature

The refined interval is as following.

Function	Target	Trigger method	Available Range	Default Value
FTP		Always / Schedule	10 ~ 86400	300
		Motion / Sound	10 ~ 86400	10
Snapshot	E-mail	Always / Schedule	30 ~ 86400	600
		Motion / Sound	30 ~ 86400	30
Video Clip	FTP	Always / Schedule	30 ~ 86400	300



DCS-942L Firmware Release Notes

		1			
			Motion / Sound	10 ~ 86400	10
		E-mail	Always / Schedule	60 ~ 86400	600
			Motion / Sound	30 ~ 86400	30
	5. Refine the dw	velling time	for SD manageme of Day/Night mod t setting as default	e switching.	d range from
V1.12_1628	 Update mydli Add SD card Add mydlink 	nk agent to warning magent versi	ion information.	accessible at boo	at time
(EU) V1.12_1608 (WW)	5. Support Direct Using follow - http://cam	Fine tune NTP failure when network is not accessible at boot time. Support Direct View Web Pages. Using following URL to get live video - http://camera_ip/vaview.htm for Windows IE - http://camera_ip/vjview.htm for non-Windows IE			
	 Enable playbe Changed the Changed the Changed the 	system der system der system der Video Type	link portal. fault time to 2012- fault IP to 192.168 e for SD card recore	01-01. .0.20. ding. It will store	both one
V1.11_1426	snapshot and video clip into the SD Card. 5. Support Encode Method for H.264 and MPEG4 Streaming. 6. Support H.264 streaming for Profile 4. 7. Improved error handling of SD hot-plug. 8. Reduces noise of low-light streaming.				
	10. Added the re minutes. 11. Enables live s	cording per streams in	patibility for IE9. riod of SD recordin Non-IE browser on vity function and se	Microsoft Windo	ws OS.





Problems Fixed:

Firmware Version	Problems Fixed
V4 25 4012	1. Disable SSLv3
V1.25_4912	2. Fixed the NIPCA XML response issue by adding <root> tag as well-format.</root>
	1. Fixed the issue that camera cannot reboot after schedule reboot is set.
V1.24_4408	2. Fixed the issue of FTP upload failure due to special characters as FTP
	password.
	1. Fixed the ONVIF compatibility issues for "ONVIF Device Manager"
V4 22 2404	2. Fixed SMTP compatibility issue of Swiss e-mail provider "bluewin.ch"
V1.23_3404	3. Fixed NTP sync issue after power on at static IP status
	4. Fixed Flicker issue in 50 HZ frequency light source environment
V1.22_2825	1. Refine Day/Night mode switching judgment.
V1.21_2811	 RTSP Authentication is default enable. Fix security vulnerability item CVE-2013-1602 from CoreSecurity.
V1.20_2219	1. Fix multiple login SD card playback error for mydlink
	Extent manual time setting list.
V1.11_1426	2. Update ActiveX version to v6216.
	Fine tune log and some log message to make sure log page display correctly.
	4. Fixed video clip failures caused by the image frame size is too large.

Known Issues:

Firmware Version	Known Issues
	1. It's recommended for users to download the latest D-ViewCam version from
V1.24_4408	mydlink portal to avoid abnormal function operation when using the
	DCS-942L Ax camera with FW v1.24_4408.

Related Documentation:

N/A

