



Firmware Version: 4.1.0.2
Published: Jun 14, 2012

Content:

Revision History and System Requirement:.....2

New Features:2

Problems Fixed:3

Known Issues:4

Related Documentation:.....4

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
Runtime: V4.1.0.2	14-Jun-2012	DWS-3160-24PC DWS-3160-24TC	A1, A2

New Features:

Firmware Version	New Features
V4.1.0.2	<ul style="list-style-type: none"> ● Numbering scheme change. In order to align the firmware version number with that of the UAPs, it is decided that the FW version would following the convention of other DWS/DWL products. The firmware naming convention dictates that so long as the first three digits of the firmware on both the UAP and DWS-3160 match, they would interoperate without issue. ● To make the RMA process more streamlined, the console command to wipe DLMS licenses from the DWS-3160 has been moved from R&D mode to user mode. This means RMA personnel would not have to enter series of complicated commands to accomplish this task. This command is hidden and isn't documented on manuals or other official documents. Only engineers and RMA personnel would have knowledge of this command. This behavior is consistent with other D-Link switches that utilize DLMS model upgrade.

Problems Fixed:

Firmware Version	Problems Fixed
V.4.1.0.2	<ol style="list-style-type: none">1. SD card compatibility issue. Prior to this release, it is found that the SD card slot on the DWS-3160 accepts a very narrow range of SD cards. This has been greatly improved with 4.1.0.2.2. In the previous release, DWL-3600APs may be discovered by DWS-3160, but all network traffic through the APs are dropped.3. Users with valid DLMS activation codes fail to activate the upgrade license. [HQ20120604000013]
V1.00.038	Initial release

Known Issues:

Firmware Version	Issues
V4.1.0.2	1. No known issue with this release.
V1.00.038	Initial release

Related Documentation:

- DWS-3160 Manual
- DWS-3160 CLI Manual