



## DAP-1513 Firmware Release Note

**Firmware: v1.01 (build b05)**

**Hardware: A1**

**Date: 06, Jul, 2011**

**Runtime Checksum: 0xBE198879**

### Problems Resolved:

1. Fix manufacturing tool issue.

### Enhancements:

1. NA
- 

Firmware: v1.00 (build b05)

Hardware: A1

Date: 30, May, 2011

Realtek Turn-key SDK version: v2.4

Wireless Driver: Fri Jan 21 14:38:36 CST 2011, RTL8192 firmware version: 10.2

ToolChain: rsdk-1.3.6-4181-EB-2.6.30-0.9.30

Runtime Checksum: 0xBE198879

### Problems Resolved:

2. WPA/WPA2 Auto, TKIP/AES Auto can work correctly.
3. ADD DNS function on static ip mode
4. WPS dualband connection 5GHz prior then try 2.4GHz

### Enhancements:

2. AP UI Spec V1.05 implement
  3. Setup Wizard V1.03 implement
  4. Wireless LED behavior update. Wireless successfully connected will be solid on, otherwise will be off.
- 

Firmware: v1.00 (build b11)

Hardware: A1

Date: 16, Mar, 2011

CPU BSP: RTL8196C, Linux version 2.6.30.9

Realtek Turn-key SDK version: v2.4

Wireless Driver: Fri Jan 21 14:38:36 CST 2011, RTL8192 firmware version: 10.2

ToolChain: rsdk-1.3.6-4181-EB-2.6.30-0.9.30

Runtime Checksum: 0x64C88582

D-Link Corporation confidential

---



Problems Resolved:

1. NA

Enhancements:

5. 1<sup>st</sup> release
-