

## **DWA-182 AC1200 Dual Band USB Adapter**

Version: 3.06b04

Hardware: A1

Date: 2016/Jan/21

Driver:

[Windows XP x86 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows XP x64 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows Vista x86 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows Vista x64 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows 7 x86 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows 7 x64 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows 8 x86 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows 8 x64 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows 8.1 x86 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows 8.1 x64 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows 10 x86 –1030.2.0731.2015 \(WHQL pass\)](#)  
[Windows 10 x64 –1030.2.0731.2015 \(WHQL pass\)](#)

### **Problems Resolved:**

1. Fix USB speed issue: USB speed limited to USB2.0 standard when operating in 5GHz band.
2. Update Microsoft WHQL certification

### **Enhancement:**

NA

### **Known Issue:**

NA