



**Firmware Version:** V4.3.0.4  
**Published:** Apr 25, 2016

**Content:**

Revision History and System Requirement:.....2

New Features: .....2

Problems Fixed: .....2

Known Issues: .....3

Related Documentation:.....4

## Revision History and System Requirement:

FW Version	Date	Model	HW	MD5 CHECKSUM
4.3.0.4	25-Apr-2016	DWL-6610AP	A1	43d2b99cc4f0fe8b1342cdcc4936af3d

## New Features:

Firmware Version	New Features
4.3.0.4	Bug Fix
4.3.0.3	<ol style="list-style-type: none"> <li>Initial release</li> <li>Recommend controller/firmware version:                      DWC-2000 FW v4403 or later version                      DWC-1000 FW v4412 or later version                      DWS-4026 FW v4.3.0.3B028 (Beta version)                      DWS-3160 FW DWS3160_Run_4_4_1_1_A01.had (Beta version)</li> <li>Root Access should be denied for admin CLI user to counter moose vulnerability</li> </ol>

## Problems Fixed:

Firmware Version	Problems Fixed
4.3.0.4	<ol style="list-style-type: none"> <li>AP rebooting continuously when we push 5GHz a/n/ac (80MHz) for few countries from wireless controller (DWC1000).</li> <li>Device is showing incorrect information in Beacons regarding the supported channel width for DWL-8610AP</li> <li>Observed AP is rebooting continuously when changing the country with static channel configuration.</li> <li>Channel list are not displayed for Australia in 40MHZ- UPPER for 5GHZ</li> <li>SSID is not broadcasting for the 20/40Mhz for the countries like Norway</li> <li>Observed common name and other fields are not proper in certificate while login through Https .</li> </ol>

	<ol style="list-style-type: none"> <li>7. Some of the DFS channels are missing in few countries.</li> <li>8. No validation of properties of SNMPV3 classes from CLI and reboot issue while adding snmpv3 target</li> <li>9. Periodically occurs high latency issue for 5G</li> <li>10. Http Certificate Expiration Date is not updating properly when AP is date is set after 2017</li> <li>11. The time should show correct with respect to the time zone selected at date and time settings page</li> <li>12. Device should allow the special characters at password from cli and GUI also</li> <li>13. The offset value should show properly at date and time setting page</li> <li>14. [SNMP] GUI look and feel issues in SNMPv3 Views, Groups, Users, Targets page</li> </ol>
4.3.0.3	<ol style="list-style-type: none"> <li>1. While capturing packets in AP on radio interface, some ICMP replies are not visible in interface captures (DBG15100154)</li> </ol>

## Known Issues:

Firmware Version	Issues
4.3.0.4	N/A
4.3.0.3	<ol style="list-style-type: none"> <li>1. AP rebooting continuously when we push 5GHz a/n/ac (80MHz) for few countries from wireless controller (DWC1000).</li> <li>2. Device is showing incorrect information in Beacons regarding the supported channel width for DWL-8610AP</li> <li>3. Observed AP is rebooting continuously when changing the country with static channel configuration.</li> <li>4. Channel list are not displayed for Australia in 40MHZ- UPPER for 5GHZ</li> <li>5. SSID is not broadcasting for the 20/40Mhz for the countries like Norway</li> <li>6. Observed common name and other fields are not proper in certificate while login through Https .</li> <li>7. Some of the DFS channels are missing in few countries.</li> <li>8. No validation of properties of SNMPV3 classes from CLI and reboot issue</li> </ol>

	while adding snmpv3 target
	9. Periodically occurs high latency issue for 5G
	10. Http Certificate Expiration Date is not updating properly when AP is date is set after 2017
	11. The time should show correct with respect to the time zone selected at date and time settings page
	12. Device should allow the special characters at password from cli and GUI also
	13. The offset value should show properly at date and time setting page
	14. [SNMP] GUI look and feel issues in SNMPv3 Views, Groups, Users, Targets page

## **Related Documentation:**

---

- DWS-x600AP Series Manual
- DWS-x600AP Series CLI Manual