



Firmware Version: 4.3.0.2_B021
Published: Jun 09, 2014

Content:

Revision History and System Requirement:.....2

New Features:2

Problems Fixed:3

Known Issues:4

Related Documentation:.....4

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
Runtime: V4.3.0.2_B016	09-Jun-14	DWL-8610AP	A1G
Runtime: V4.3.0.2_B021	13-Oct-14	DWL-8610AP	A1G

New Features:

Firmware Version	New Features
V4.3.0.2_B016	Initial release
V4.3.0.2_B021	No new features

Problems Fixed:

Firmware Version	Problems Fixed
V4.3.0.2_B021	<ol style="list-style-type: none"> 1. Fix 80MHz support for certain countries [HQ20140925000003] 2. Random reboot [DEUR20140910000012] 3. Naming issue on the GUI under managed mode [HQ20140919000011] 4. MAC white list issue [DGC20140730000001] 5. Issue with newer Apple devices where connectivity might be loss after returning from sleep state [HQ20140718000002] 6. Fix scheduler support [HQ20140821000006] 7. Slow throughput with certain country code [HQ20140825000011] 8. Slow throughput with VLAN tags [HQ20140725000005] 9. Incorrect Bootevn -d altbootver [HQ20140806000001] 10. Change DDP packet from every 10s to 30s [HQ20140626000015] 11. Change ARP packet from 10s to 30s [HQ20140626000015] 12. AP will enter anon-responsive state under certain circumstances [HQ20140627000005]
V4.3.0.2_B016	Initial release

Known Issues:

Firmware Version	Issues
V4.3.0.2_B021	None
V4.3.0.2_B016	None

Related Documentation:

- DWS-x600AP Series Manual
- DWS-x600AP Series CLI Manual