



Driver Version: v4.10
Published: Dec 19, 2012

These release notes include important information about D-Link LAN adapter driver revisions. Please follow below steps for driver upgrades:

- Please refer to [Revision History and System Requirement](#) for driver and hardware version matrix.
- If you are installing a new LAN adapter, please check the hardware version on the device label; make sure that your adapter meets the requirement of this driver version.
- Please install the drivers before inserting LAN adapter into the computer's PCI/PCIe slot.

For more information regarding our LAN adapter products, please refer to [Related Documentation](#).

You can also download the LAN adapter drivers from <http://tsd.dlink.com.tw>.

Content:

Revision History and System Requirement:	2
New Features:	2
Problem Fixed:	3
Known Issues:	4
Related Documentation:	4

Revision History and System Requirement:

Driver Version	Date	Model	Hardware Version
V4.10	19-Dec-12	DGE-560SX	B1 (not compatible to A1)
V4.00	27-Apr-12	DGE-560SX	B1 (not compatible to A1)
V3.00	21-Oct-09	DGE-560SX	A1
V2.00	05-July-07	DGE-560SX	A1
V1.00	12-Oct-06	DGE-560SX	A1

Note:

Since the hardware version A1 and B1 are not compatible, driver v4.00 or later versions do not work on A1.

New Features:

Driver Version	New Features
V4.10	<p>1. Support the following Operating Systems:</p> <p>Microsoft Windows 8 (32/64-bit): v15.4.0.17 Microsoft Windows 7 (32/64-bit): v15.4.0.17 Microsoft Windows Vista (32/64-bit): v15.4.0.17 Microsoft Windows Server 2008 (32/64-bit): v15.4.0.17 Microsoft Windows Server 2003 (32/64-bit): v15.2.0.4 Microsoft Windows XP (32/64-bit): v15.2.0.4</p> <p>NDIS2: v15.0.1 Netware Server 4.x/5.x/6.x: v14.61 Netware DOS ODI: v15.0.1 Linux kernel 2.4.x/2.6.x: v3.12</p> <p>2. Management Utility Broadcom Advanced Control Suite</p>
V4.00	<p>1. Support the following Operating Systems:</p> <p>Microsoft Windows 7 (32/64-bit): v15.0.0.21 Microsoft Windows Vista (32/64-bit): v15.0.0.21 Microsoft Windows Server 2008 (32/64-bit): v15.0.0.21 Microsoft Windows Server 2003 (32/64-bit): v15.0.0.9 Microsoft Windows XP (32/64-bit): v15.0.0.9</p> <p>NDIS2: v15.0.1 Netware Server 4.x/5.x/6.x: v14.61 Netware DOS ODI: v15.0.1 Linux kernel 2.4.x/2.6.x: v3.12</p> <p>2. Management Utility Broadcom Advanced Control Suite</p> <p>Note:</p>

	Since the hardware version A1 and B1 are not compatible, driver v4.00 or later versions do not work on A1.
V3.00	<p>1. Support the following Operating Systems: Windows 7 x86/64 (WHQL passed) : v11.11.3.2 Windows Server 2008 x86/64 (WHQL passed): v10.52.2.3</p> <p>2. Update Windows Vista x86/64, XP x86/64 and 2003 x86/64 driver version to v10.52.2.3</p>
V2.00	<p>Support the following Operating Systems: Microsoft Windows Vista x86: v9.15.2.3 Microsoft Windows Vista x64: v9.15.2.3 Microsoft Windows 2000: v8.64.1.3 Microsoft Windows 2003: v8.64.1.3 Microsoft Windows 2003 x64 Edition: v8.39.10.3 Microsoft Windows XP: v8.64.1.3 Microsoft Windows XP x64 Edition: v8.39.10.3 Linux for Kernel 2.4.x, 2.6.x: v8.35.2.3 D-Link Control Program (for Win 2k/Server 2003/XP): v5.60.4.3 D-Link Control Program (for Win 2003 x64/XP x64): v6.15.3.3 SNMP Agent (for Win 2k/Server 2003/2003 x64/XP/XP x64): v1.1.0.60823</p>
V1.00	<p>Support the following Operating Systems: Microsoft Windows 2000,2000 Server: v8.39.10.3 Microsoft Windows 2003: v8.39.10.3 Microsoft Windows 2003 x64 Edition: v8.39.10.3 Microsoft Windows XP: v8.39.10.3 Microsoft Windows XP x64 Edition: v8.39.10.3 Linux for Kernel 2.4.x, 2.6.x: v8.35.2.3 CPA: v5.60.2.3 SNMP Agent: v1.1.0.60823 Autorun: v4.8.0.1</p>

Problem Fixed:

Driver Version	Problems Fixed
V4.10	N/A
V4.00	N/A
V3.00	N/A
V2.00	N/A
V1.00	N/A

Known Issues:

Driver Version	Problems Fixed
V4.10	N/A
V4.00	N/A
V3.00	N/A
V2.00	N/A
V1.00	N/A

Related Documentation:

- DGE-560SX Quick Installation Guide
- DGE-560SX User Manual