



Driver Version: V1.00
Published: Mar 7, 2014

These release notes include important information about D-Link LAN adapter driver revisions. Please follow below steps for driver upgrades:

- Please refer to [Revision History and Requirement](#) for driver and hardware version matrix.
- If you are installing a new LAN adapter, please check the hardware version on the device label. Make sure that your adapter meets the requirement of this driver version.
- Please install the drivers before inserting LAN adapter into the computer's PCI/PCIe slot.

For more detailed information regarding our LAN adapter products, please refer to [Related Documentation](#).

You can also download the LAN adapter drivers from <http://tsd.dlink.com.tw>.

Content:

Revision History and Requirement:	2
New Features:	2
Problem Fixed:	2
Known Issues:	2
Related Documentation:	2

Revision History and Requirement:

Driver Version	Date	Model	Hardware Version
V1.00	7-Mar-2014	DXE-810S	A1

New Features:

Driver Version	Software content
V1.00	<p>Support the following Operating Systems:</p> <p>Windows 8 (32/64 bits), 7 (32/64 bits): V4.3.404.117 Windows Server 2012, 2012R2, 2008R2: V4.3.404.117 Windows Hyper-V: V4.3.404.117 Linux kernel 2.4.x ~ 3.x.x: V1.1.6.8_D VMWare ESXi 4.x: V400.1.1.6.8-1OEM</p>

Problem Fixed:

Driver Version	Problems Fixed
V1.00	N/A

* D-Link tracking number is enclosed in ()

Known Issues:

Driver Version	Know Issues
V1.00	The digital signature of TN4022mp_64.sys and TN4022mp_32.sys are failed.

Related Documentation:

- DXE-810S Quick Installation Guide v1.00
- DXE-810S Manual v1.01