



Firmware Version: V1.02
Prom Code Version: N/A
Published Date: 2013/06/20

Content:

Upgrading Instructions:.....	2
New Features:.....	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	4

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2013/12/04	DNR-202L	A1
V1.01	2014/06/20	DNR-202L	A1
V1.02	2014/09/18	DNR-202L	A1

Upgrading Instructions:

1. Upgrading by using Web-UI

New Features:

Fireware Version	New Features
V1.00.22	1. New model MP FW release
V1.01.00	1. Update the mydlink agent to 2.0.17-b45
V1.02.01	<ol style="list-style-type: none"> 1. Update the mydlink agent to V2.0.18-b08 2. Add Universal Model

Enhancements:

Firmware Version	Problems Fixed
V1.00.22	N/A
V1.01.00	<ol style="list-style-type: none"> 1. Landing page add setting page and even functions by US HQ. 2. Modify the live icon description.
V1.02.01	1. Add Camera support: DCS-930LB1/ DCS-932LB1/ DCS-942LB1/ DCS-6004L/ DCS-6005L/

Problems Fixed:

Firmware Version	Problems Fixed
V1.00.22	N/A
V1.01.00	<ol style="list-style-type: none"> 1. Fixed DLAB Bug DBG13100305: When keying right account and wrong password to register, it would not show any warning message and pass to the next flow. 2. Fixed DLAB Bug DBG13080170: Audio is strange on DCS-931L, DCS-933L and DCS-5020L.

	<ol style="list-style-type: none"> 3. Fixed DLAB Bug DBG13090288: Playback could not play recording files by speeding up to 1/4/8/16/32 normally. It would stop after a while.(Test with IE8, IE9, Firefox and Chrome) 4. Fixed DLAB Bug DBG13080155: Almost functions could not be worked when first time log in DUT with browser IE7. 5. Fixed DLAB Bug DBG13080041: Playback could not play recording files by speeding up to 1/4/8/16/32 normally. It would stop after a while.(Test with IE8 & IE9) 6. Fixed DLAB Bug DBG13020011: Live view would be in black after enable full screen and glance for a long term. 7. Fixed D-Track HQ20140107000013: Export avi the video and audio will not sync. 8. Fixed D-Track HQ20140113000014: I saw from log that record on 11 Jan. has been deleted due to disk full. However, when I access playback and selected 11 Jan. it still shows red line with records. I selected it to playback, it will show blank on screen. 9. Fixed D-Track HQ20140116000020: The image enhancement button always gray out 10. Fixed D-Track HQ20140128000008: DNR-202L not work playback function over IE11 and Firefox v26.0
V1.02.01	<ol style="list-style-type: none"> 1. Fixed DLAB Bug DBG13020096: Convert 2 hours recording would cause the browser carshed. 2. Fixed DLAB Bug DBG13090341: Recording of all channels would stop for a while by itself but there is no log about that. 3. Fixed DLAB Bug DBG14050136: Not translate "OSD setting" on live video and playback page in all supported languages. 4. Fixed DLAB Bug DBG14050187: Both Safari and firefox cannot display normally in live video of mydlink. 5. Fixed DLAB Bug DBG13090343: Some sentences are all bold of description in spanish language. 6. Fixed DLAB Bug DBG13090314: Export files are not complete. Export 1 hour video but just 6 exported files.(Watermark/ Standard/ AVI file)(Test with DCS-932 and DCS-6818B1) 7. Fixed DLAB Bug DBG14050133: Live video could not be watched on Opera browser normally.(Opera 21.0.1432.67) 8. Fixed DLAB Bug DBG13090356: Change fixed quality of DCS-3715 to "very high" but it shows "customize" on DCS-3715 UI. 9. Fixed DLAB Bug DBG14050134: Live video could not be watched on Safari browser in Mac OS. 10. Fixed DLAB Bug DBG13020075: No waring message would popup when convert a recording file without setting the cue-in and cue-out 11. Fixed DLAB Bug DBG13020016: FW version on the title of page wouldn't be properly. 12. Fixed DLAB Bug DBG13020018: Time bar in PLAYBACK couldn't be visible when browse by non-IE browsers 13. Fixed DLAB Bug DBG13020019: Some typos are in the SUPPORT pag 14. Fixed the mydlink Bug 8232: There is no live video and playback video on Mac 10.9/ safari 7 15. Fixed the mydlink Bug10943: Couldn't watch live view on DNR-202L after update JAVA 7 to 67

Known Issues:

Firmware Version	Known Issues
------------------	--------------

V1.00.22	N/A
V1.01.00	1. Safari above 6.1 will not display the video on MAC os.
V1.02.01	1. Export AVI function will not work on MAC OS.

Related Documentation:

N/A