



DHP-W306AV Firmware Release Notes

Firmware: FW change from 1.01 to 1.02

Hardware: A2

Date: 2011/10/13

Problems Resolved:

None

Enhancements:

- 1- Support D-Link one touch AP configuration to copy the SSID and encryption setting from other router or AP.
- 2- Support power saving mode, and it can be closed by web UI.

Known Issues:

None