

Model: DAP-1360

Firmware version: 2.0.2

Build time: Thu Jun 27 15:46:12 MSK 2013

File name: 20130627_1536_DAP_1360D1_2.0.2_sdk-master.bin

Added Features

1. Auto-upgrade firmware

Fixed Features

1. Router mode: WAN connection issue - Unknown error after disconnection LAN (eth_port)
2. Router mode: WAN: Clone MAC address
3. Router mode: WiFi (WISP) client: re-connect after reboot of device
4. AP mode: throughput LAN-to-LAN
5. AP mode: WiFi client: symbol "space" in SSID; symbol "#" in WPA preshared key; WEP 64 bit ASCII/HEX
6. AP mode: LAN settings: Gateway

Specific Features

1. None

System requirements:

Computer with:

Windows® 8, Windows® 7, Windows Vista®, Windows®XP SP3, or Mac OS® X (v10.4)

Internet Explorer® v8 or Mozilla® Firefox® v17.0

Network Interface Card

For Internet Access:

Cable or DSL Modem

Subscription with an Internet Service Provider (ISP)