

Model: DAP-1155

Firmware version: 2.0.10

Build time: Thu Aug 22 17:21:53 MSK 2013

File name: 20130822_1715_DAP_1155B1_2.0.10_sdk-master.bin

Added Features

1. None

Fixed Features

1. Router mode: PPPoE re-connect
2. Router mode: PPTP/L2TP routing table issue
3. led wifi issue
4. syslog issue

Specific Features

1. None

System requirements:

Computer with:

Windows® 8, Windows® 7, Windows Vista®, Windows®XP SP3, or Mac OS® X (v10.4)

Internet Explorer® v8 or Mozilla® Firefox® v17.0

Network Interface Card

For Internet Access:

Cable or DSL Modem

Subscription with an Internet Service Provider (ISP)