



DAP-1320 B1 Firmware Release Note

Firmware: v2.01

Hardware: B1

Date: 2014/7/28

Note:

1. The firmware version is advanced to v2.01

Problems Resolved:

1. Fixed it was possible to make other clients disconnected during WPS process.

Enhancements:

None

Known Issues:

None