



BUILDING NETWORKS FOR PEOPLE

DWA-140 B3 RangeBooster N USB Adapter Firmware Release Notes

Firmware: UI 2.6.2.0

Hardware: B3 D-4.2.2.0 UI-2.6.2.0

Date: 2012/03/22

Driver: 4.2.2.0

System Requirement:

Mac OS X v10.5, 10.6, 10.7

Software Supported:

For Mac OS X 10.7.X:

D-Link DWA140 OS-10.7\ D-Link DWA140.pkg

For Mac OS X 10.6.X:

D-Link DWA140 OS-10.6\ D-Link DWA140.pkg

For Mac OS X 10.5.X:

D-Link DWA140 OS-10.5\ D-Link DWA140.mpkg

Problems Resolved:

1. Support Mac OS X v10.7

Known issue:

NA

Firmware: UI 2.5.1.0

Hardware: B3 D-4.1.6.0 UI-2.5.1.0

Date: 2011/08/23

Driver: 4.1.6.0

System Requirement:

Mac OS X v10.4, v10.5, 10.6

Software Supported:

For Mac OS X 10.6.X:

D-Link DWA140 OS-10.6\ D-Link DWA140.pkg

For Mac OS X 10.5.X:

D-Link DWA140 OS-10.5\ D-Link DWA140.pkg

For Mac OS X 10.4.X:

D-Link DWA140 OS-10.4\ D-Link DWA140.mpkg

Problems Resolved:

D-Link Corporation confidential



BUILDING NETWORKS FOR PEOPLE

1st release

Known issue:

NA
